



Vehicle History Report



YS3DF78N6V7006126
SAAB SAAB 900

[View Report Guide](#)

[View Terms and Conditions](#)

Data: 2015-12-28 09:30:29

ID: 5680f2fc-d6b4-4638-9a0d-34ed0a0a0a4f

VIN Decoder

This section contains a set of technical details.

Make:	SAAB
Model:	SAAB 900
Year:	1997
Body style:	2-DOOR CONVERTIBLE (CV)
Engine type:	B204L 4-INLINE, TURBO, PETROL, TURBO (B204 L)
Transmission:	4-SPEED AUTOMATIC
Market:	MODEL SERIES III, DRIVER AND PASSENGER AIRBAGS
Version:	SE
Body style:	CONVERTIBLE
Number of doors:	2
Seats:	4
Vehicle class:	MID-SIZE CAR
Vehicle type:	MEDIUM-LARGE CARS
Model year:	1997
Assembly plant:	NYSTAD, FINLAND (SWEDEN)
Checksum:	VALID
Engine code:	B202L
Engine configuration:	INLINE ENGINE
Engine type:	L4
Engine_version:	ECOPOWER
Engine head:	DOHC

Valves:	16
Cylinders:	4
Displacement SI:	1985 CM3
Displacement CID:	121 CID
Displacement nominal:	2.0 L
Horsepower:	185 HP
Kilowatts:	138 KW
Fuel type:	PETROL
Driveline:	FWD
Transmission type:	AUTOMATIC
Gears:	5
Country of origin:	SWEDEN / EUROPE
Line:	900
Restraint system:	SE, CSE W/DUAL AIRBAGS

Vehicle Equipment

This section contains a list of vehicle equipment options.

NO DATA

Damage History

This section contains registry of known vehicle damages.

NO DATA

Mileage History

This section contains a set of known mileages of checked vehicle.

#	Date	Mileage
1	2006-11-22	137351 mi km
2	2005-03-29	125839 mi km

Internet History

This section contains a data about vehicle gathered form the Internet.

2006-11-22	Description	Vehicle offered at salvage auto auction. Odometer status: Actual. Odometer reading is believed to be the true and actual mileage. Possible defects/damages: front end damage.
	Odometer	137351 mi
2005-03-29	Description	Vehicle offered at salvage auto auction. Odometer status: Actual. Odometer reading is believed to be the true and actual mileage. Possible defects/damages: many defects/damages . Legal status of the vehicle: title: SALVAGE.
	Odometer	125839 mi

Services History

This section contains history of known services.

NO DATA



















Check History

This section contains informations about geo-localisation of checks in our service of this particular VIN. You can also trace this history on map (just click Show on Map button below).

NO DATA

Databases of stolen vehicles

This section warns you if checked vehicle is wanted by police in selected countries.

	Register of stolen vehicles of Canadian Police		No entry
	Internet register of stolen vehicles CrimiMail		No entry
	Register of stolen vehicles of Czech Police		No entry
	Internet register of stolen vehicles Germany		Database unavailable
	Internet register of stolen vehicles Norway		No entry
	Register of stolen vehicles of Italian Police		No entry
	Internet register of stolen vehicles Kaynine		No entry
	Register of stolen vehicles of Lithuanian Police		No entry
	Register of stolen vehicles of Dutch Police		No entry

	Register of stolen vehicles of Romanian Police		Database unavailable
	Internet register of stolen vehicles Sweden		No entry
	Register of stolen vehicles of Slovenian Police		No entry
	Register of stolen vehicles of Slovak Police		No entry
	Register of stolen vehicles IAATI / VIN-Info		No entry

Production Defects

This section warns you against the defects reported by manufacturer.

NO DATA

Vehicle Manufacturer

This section contains informations about the manufacturer of checked vehicle.

Entry Date	Name	Address	Country
1980-08-13	Saab-Scania Ab	Trollhattan, Sweden	Sweden

Vehicle Photos

This section is a gallery of photos of checked vehicle.

Source no. **1/1** of **2010-12-04**











Disclaimer

Final information: the amount of data available in each section of the report depends on the VIN number to be checked and is provided prior to the purchase of the report. VIN-INFO collects the information from public sources available on the Internet, using its own expert system. The information presented in the reports are a compilation of data gathered by the VIN-INFO expert system and may duplicate the source errors. We do everything in our power to ensure that our translation system provides complete and logical translations to all languages, respecting the rules of grammar. However, taking into consideration the automation of the system, the generated translations may contain words in foreign languages or linguistic errors. Please note that the expert system designed to search information on VIN-INFO vehicles must be treated only as an auxiliary tool and cannot constitute a basis for any claims. The report with the results must be always compared to the actual state and the contents of the documents.

 [Mobile version](#)

Copyright © 2001-2015 [VIN-Info](#) Sp. z o.o.